



Loes Enterprises, Inc

1457 Iglehart Ave
St. Paul, Mn 55104

Fax: 651-646-3067

800-869-1088

WWW.Loesent.com

E-mail Loes@Loesent.com

PH: 651-646-1385

Basic Usage Instructions

- ☞ **Prepare surface so that is clean and dry. A smooth surface gives better release.**
- ☞ **Shake or stir MRV 1000 before using to assure the uniform dispersion of its active ingredient. (MRV 1000 is dispersed in an isopropanol alcohol solution, keep away from flame & sparks)**
- ☞ **Apply MRV 1000 to surfaces where release is needed and let air dry. When MRV 1000 is dry, a white powdery film will appear. (It is important to use adequate ventilation when using this product.)**
- ☞ **Spot heat MRV 1000 to form a more durable coating if needed, the melting point of MRV's active ingredient is 575° F.**
- ☞ **Apply Varnish in the Standard Procedure.**
- ☞ **Peel cured varnish film off from MRV 1000 treated areas.**